Fabric Air Permeability Tester LMAT-504

Labmate Fabric Air Permeability Tester measures air resistance in fabrics with a range of 0.1–12,000 mm/s and a pressure range of 1–4000 Pa. It features a touch control panel, integrated software, and caster wheels for mobility. test standards and offers easy sample clamping and data storage.