



System Log

Index Log Content

```
1 0000:System: The device initialization succeeded.
2 0015:DHCPs: 1:0xf07bcb212156, NAK in request.
3 0015:DHCPs: 1:0xf07bcb212156, 192.168.1.100, ACK in request.
4 0017:PPPoE: Automatically dialing on demand.
5 0017:PPPoE: Sending PADI.
6 0017:PPPOE_TAG_SVC_NAME=null
7 0017:The first service name is accepted.
8 0017:PPPOE: reserve AC-COOKIE tag.
9 0017:PPPOE: receive HOST-UNIQUE tag.
10 0017:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E55EA5.
11 0017:PPPoE: Sending PADR.
12 0017:PPPoE: Received PADS,Session-ID=0x2D9,AC-MAC=002590E55EA5.
13 0017:LCP tx Req,MRU=05C8;Magic=00001ABF;
14 0017:LCP RX Req,MRU=05D4;Auth=C023;Magic=BE71E5EB;
15 0017:LCP tx Ack,MRU=05D4;Auth=C023;Magic=BE71E5EB;
16 0018:LCP tx Req,MRU=05C8;Magic=00001ABF;
17 0018:LCP RX Ack,MRU=05C8;Magic=00001ABF;
18 0018:PAP IDLE -> REQ.
19 0018:LCP RX echo req before ppp is up.
20 0018:PAP tx Req.
21 0019:PAP: PAP authentication failed.
22 0020:PPPoE: Sending PADI.
23 0020:Invalid PADT packt received.
24 0020:PPPOE_TAG_SVC_NAME=null
25 0020:The first service name is accepted.
26 0020:PPPOE: reserve AC-COOKIE tag.
27 0020:PPPOE: receive HOST-UNIQUE tag.
28 0020:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E56419.
29 0020:PPPoE: Sending PADR.
30 0020:PPPoE: Received PADS,Session-ID=0x13,AC-MAC=002590E56419.
31 0020:LCP tx Req,MRU=05C8;Magic=0000578D;
32 0021:LCP RX Req,MRU=05D4;Auth=C023;Magic=3A236666;
33 0021:LCP tx Ack,MRU=05D4;Auth=C023;Magic=3A236666;
34 0021:LCP tx Req,MRU=05C8;Magic=0000578D;
35 0021:LCP RX Ack,MRU=05C8;Magic=0000578D;
36 0021:PAP IDLE -> REQ.
37 0021:LCP RX echo req before ppp is up.
38 0022:PAP tx Req.
39 0023:PAP: PAP authentication failed.
40 0023:DHCPs: 1:0x8c3ae38600a4, NAK in request.
41 0024:PPPoE: Sending PADI.
42 0024:Invalid PADT packt received.
```

43 0024:PPPOE_TAG_SVC_NAME=null
44 0024:The first service name is accepted.
45 0024:PPPOE: reserve AC-COOKIE tag.
46 0024:PPPOE: receive HOST-UNIQUE tag.
47 0024:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E55E87.
48 0024:PPPoE: Sending PADR.
49 0024:PPPoE: Received PADS,Session-ID=0x4F3,AC-MAC=002590E55E87.
50 0024:LCP tx Req,MRU=05C8;Magic=00004907;
51 0024:LCP RX Req,MRU=05D4;Auth=C023;Magic=6DF55573;
52 0024:LCP tx Ack,MRU=05D4;Auth=C023;Magic=6DF55573;
53 0024:LCP tx Req,MRU=05C8;Magic=00004907;
54 0024:LCP RX Ack,MRU=05C8;Magic=00004907;
55 0024:PAP IDLE -> REQ.
56 0024:LCP RX echo req before ppp is up.
57 0025:PAP tx Req.
58 0026:PAP: PAP authentication failed.
59 0027:PPPoE: Sending PADI.
60 0027:Invalid PADT packt received.
61 0027:PPPOE_TAG_SVC_NAME=null
62 0027:The first service name is accepted.
63 0027:PPPOE: reserve AC-COOKIE tag.
64 0027:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E56419.
65 0027:PPPoE: Sending PADR.
66 0027:PPPoE: Received PADS,Session-ID=0x15B8,AC-MAC=002590E56419.
67 0027:LCP tx Req,MRU=05C8;Magic=000012B2;
68 0027:LCP RX Req,MRU=05D4;Auth=C023;Magic=35076AF9;
69 0027:LCP tx Ack,MRU=05D4;Auth=C023;Magic=35076AF9;
70 0028:LCP tx Req,MRU=05C8;Magic=000012B2;
71 0028:LCP RX Ack,MRU=05C8;Magic=000012B2;
72 0028:PAP IDLE -> REQ.
73 0028:Send Identification (1).
74 0028:Send Identification (2).
75 0028:LCP RX echo req before ppp is up.
76 0028:PAP tx Req.
77 0029:DHCPs: 1:0x8c3ae38600a4, 192.168.1.101, ACK in request.
78 0029:PAP: PAP authentication failed.
79 0031:PPPoE: Sending PADI.
80 0031:Invalid PADT packt received.
81 0031:PPPOE_TAG_SVC_NAME=null
82 0031:The first service name is accepted.
83 0031:PPPOE: reserve AC-COOKIE tag.
84 0031:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E56419.
85 0031:PPPoE: Sending PADR.
86 0031:PPPoE: Received PADS,Session-ID=0xCDD,AC-MAC=002590E56419.
87 0031:LCP tx Req,MRU=05C8;Magic=00002C88;
88 0031:LCP RX Req,MRU=05D4;Auth=C023;Magic=C6B311AF;
89 0031:LCP tx Ack,MRU=05D4;Auth=C023;Magic=C6B311AF;

90 0032:LCP tx Req,MRU=05C8;Magic=00002C88;
91 0032:LCP RX Ack,MRU=05C8;Magic=00002C88;
92 0032:PAP IDLE -> REQ.
93 0032:LCP RX echo req before ppp is up.
94 0033:PAP tx Req.
95 0034:PAP: PAP authentication failed.
96 0035:PPPoE: Sending PADI.
97 0035:Invalid PADT packt received.
98 0035:PPPOE_TAG_SVC_NAME=null
99 0035:The first service name is accepted.
100 0035:PPPOE: reserve AC-COOKIE tag.
101 0035:PPPOE: receive HOST-UNIQUE tag.
102 0035:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E56419.
103 0035:PPPoE: Sending PADR.
104 0035:PPPoE: Received PADS,Session-ID=0xF73,AC-MAC=002590E56419.
105 0035:LCP tx Req,MRU=05C8;Magic=00003998;
106 0036:LCP RX Req,MRU=05D4;Auth=C023;Magic=A3069F9B;
107 0036:LCP tx Ack,MRU=05D4;Auth=C023;Magic=A3069F9B;
108 0036:LCP tx Req,MRU=05C8;Magic=00003998;
109 0036:LCP RX Ack,MRU=05C8;Magic=00003998;
110 0036:PAP IDLE -> REQ.
111 0036:LCP RX echo req before ppp is up.
112 0037:PAP tx Req.
113 0038:PAP: PAP authentication failed.
114 0039:PPPoE: Sending PADI.
115 0039:Invalid PADT packt received.
116 0039:PPPOE_TAG_SVC_NAME=null
117 0039:The first service name is accepted.
118 0039:PPPOE: reserve AC-COOKIE tag.
119 0039:PPPOE: receive HOST-UNIQUE tag.
120 0039:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E56419.
121 0039:PPPoE: Sending PADR.
122 0039:PPPoE: Received PADS,Session-ID=0x363,AC-MAC=002590E56419.
123 0039:LCP tx Req,MRU=05C8;Magic=00002F9B;
124 0039:LCP RX Req,MRU=05D4;Auth=C023;Magic=90EE10A7;
125 0039:LCP tx Ack,MRU=05D4;Auth=C023;Magic=90EE10A7;
126 0040:LCP tx Req,MRU=05C8;Magic=00002F9B;
127 0040:LCP RX Ack,MRU=05C8;Magic=00002F9B;
128 0040:PAP IDLE -> REQ.
129 0040:LCP RX echo req before ppp is up.
130 0040:PAP tx Req.
131 0041:PAP: PAP authentication failed.
132 0042:PPPoE: Sending PADI.
133 0042:Invalid PADT packt received.
134 0042:PPPOE_TAG_SVC_NAME=null
135 0042:The first service name is accepted.
136 0042:PPPOE: reserve AC-COOKIE tag.

137 0042:PPPOE: receive HOST-UNIQUE tag.
138 0042:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E55EA5.
139 0042:PPPoE: Sending PADR.
140 0042:PPPoE: Received PADS,Session-ID=0x1587,AC-MAC=002590E55EA5.
141 0042:LCP tx Req,MRU=05C8;Magic=00005263;
142 0043:LCP RX Req,MRU=05D4;Auth=C023;Magic=AE54094C;
143 0043:LCP tx Ack,MRU=05D4;Auth=C023;Magic=AE54094C;
144 0043:LCP tx Req,MRU=05C8;Magic=00005263;
145 0043:LCP RX Ack,MRU=05C8;Magic=00005263;
146 0043:PAP IDLE -> REQ.
147 0043:LCP RX echo req before ppp is up.
148 0044:PAP tx Req.
149 0045:PAP: PAP authentication failed.
150 0045:CANNOT got any correct dial mode, the dial interval is 28 s.
151 0046:DHCPs: 1:0x90a4de5e4e05, NAK in request.
152 0046:PPPoE: Automatically dialing on demand.
153 0047:PPPoE: Sending PADI.
154 0047:Invalid PADT packet received.
155 0047:PPPOE_TAG_SVC_NAME=null
156 0047:The first service name is accepted.
157 0047:PPPOE: reserve AC-COOKIE tag.
158 0047:PPPOE: receive HOST-UNIQUE tag.
159 0047:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E5645D.
160 0047:PPPoE: Sending PADR.
161 0047:DHCPs: 1:0x90a4de5e4e05, 192.168.1.103, ACK in request.
162 0047:PPPoE: Received PADS,Session-ID=0x6EB,AC-MAC=002590E5645D.
163 0047:LCP tx Req,MRU=05C8;Magic=00007167;
164 0047:LCP RX Req,MRU=05D4;Auth=C023;Magic=D5AA91A7;
165 0047:LCP tx Ack,MRU=05D4;Auth=C023;Magic=D5AA91A7;
166 0047:LCP tx Req,MRU=05C8;Magic=00007167;
167 0047:LCP RX Ack,MRU=05C8;Magic=00007167;
168 0047:PAP IDLE -> REQ.
169 0047:LCP RX echo req before ppp is up.
170 0048:PAP tx Req.
171 0049:PAP: PAP authentication failed.
172 0050:PPPoE: Sending PADI.
173 0050:Invalid PADT packet received.
174 0050:PPPOE_TAG_SVC_NAME=null
175 0050:The first service name is accepted.
176 0050:PPPOE: reserve AC-COOKIE tag.
177 0050:PPPOE: receive HOST-UNIQUE tag.
178 0050:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E55E87.
179 0050:PPPoE: Sending PADR.
180 0050:PPPoE: Received PADS,Session-ID=0x6EA,AC-MAC=002590E55E87.
181 0050:LCP tx Req,MRU=05C8;Magic=0000767E;
182 0050:LCP RX Req,MRU=05D4;Auth=C023;Magic=FF97C72A;
183 0050:LCP tx Ack,MRU=05D4;Auth=C023;Magic=FF97C72A;

184 0051:LCP tx Req,MRU=05C8;Magic=0000767E;
185 0051:LCP RX Ack,MRU=05C8;Magic=0000767E;
186 0051:PAP IDLE -> REQ.
187 0051:LCP RX echo req before ppp is up.
188 0052:PAP tx Req.
189 0053:PAP: PAP authentication failed.
190 0054:PPPoE: Sending PADL.
191 0054:Invalid PADT packet received.
192 0054:PPPOE_TAG_SVC_NAME=null
193 0054:The first service name is accepted.
194 0054:PPPOE: reserve AC-COOKIE tag.
195 0054:PPPOE: receive HOST-UNIQUE tag.
196 0054:PPPoE: Received PADO,AC-Name=DIGI,AC-MAC=002590E5645D.
197 0054:PPPoE: Sending PADR.
198 0054:PPPoE: Received PADS,Session-ID=0xA79,AC-MAC=002590E5645D.
199 0054:LCP tx Req,MRU=05C8;Magic=00004D0E;
200 0054:LCP RX Req,MRU=05D4;Auth=C023;Magic=5E99464A;
201 0054:LCP tx Ack,MRU=05D4;Auth=C023;Magic=5E99464A;
202 0054:LCP tx Req,MRU=05C8;Magic=00004D0E;
203 0054:LCP RX Ack,MRU=05C8;Magic=00004D0E;
204 0054:PAP IDLE -> REQ.
205 0054:LCP RX echo req before ppp is up.
206 0055:PAP tx Req.
207 0055:PAP: PAP authentication succeeded.
208 0055:IPCP tx Req,IP=00000000;DNS1=00000000;DNS2=00000000;
209 0055:IPCP RX Req,IP=0A000001;
210 0055:IPCP tx Ack,IP=0A000001;
211 0055:IPCP RX Nak,IP=55EE49F1;DNS1=C16E3808;DNS2=C16E3904;
212 0055:IPCP tx Req,IP=55EE49F1;DNS1=C16E3808;DNS2=C16E3904;
213 0055:IPCP RX Ack,IP=55EE49F1;DNS1=C16E3808;DNS2=C16E3904;
214 0055:PPP connection succeeded. 85.238.73.241 .
215 0060:DHCP client tx discover(B).
216 0086:Flags was changed to be 0x0.
217 0110:PPPOE: invalid server.
218 0144:Flags was changed to be 0x0.
219 0176:DHCP discovery timeout.
220 0180:DHCP client tx discover(B).
221 0206:Flags was changed to be 0x0.
222 0263:Flags was changed to be 0x0.
223 0295:DHCP discovery timeout.
224 0299:DHCP client tx discover(B).
225 0325:Flags was changed to be 0x0.
226 0382:Flags was changed to be 0x0.
227 0414:DHCP discovery timeout.
228 0418:DHCP client tx discover(B).
229 0444:Flags was changed to be 0x0.
230 0501:Flags was changed to be 0x0.

231 0533:DHCP discovery timeout.
232 0537:DHCP client tx discover(B).
233 0563:Flags was changed to be 0x0.
234 0620:Flags was changed to be 0x0.
235 0652:DHCP discovery timeout.
236 0656:DHCP client tx discover(B).
237 0682:Flags was changed to be 0x0.
238 0739:Flags was changed to be 0x0.
239 0771:DHCP discovery timeout.
240 0775:DHCP client tx discover(B).
241 0801:Flags was changed to be 0x0.
242 0858:Flags was changed to be 0x0.
243 0890:DHCP discovery timeout.
244 0894:DHCP client tx discover(B).
245 0920:Flags was changed to be 0x0.
246 0977:Flags was changed to be 0x0.
247 1009:DHCP discovery timeout.
248 1013:DHCP client tx discover(B).
249 1039:Flags was changed to be 0x0.
250 1096:Flags was changed to be 0x0.
251 1128:DHCP discovery timeout.
252 1132:DHCP client tx discover(B).
253 1158:Flags was changed to be 0x0.
254 1215:Flags was changed to be 0x0.
255 1247:DHCP discovery timeout.
256 1251:DHCP client tx discover(B).
257 1277:Flags was changed to be 0x0.
258 1334:Flags was changed to be 0x0.
259 1366:DHCP discovery timeout.
260 1370:DHCP client tx discover(B).
261 1396:Flags was changed to be 0x0.
262 1453:Flags was changed to be 0x0.
263 1485:DHCP discovery timeout.
264 1489:DHCP client tx discover(B).
265 1515:Flags was changed to be 0x0.
266 1572:Flags was changed to be 0x0.
267 1604:DHCP discovery timeout.
268 1608:DHCP client tx discover(B).
269 1634:Flags was changed to be 0x0.
270 1691:Flags was changed to be 0x0.
271 1723:DHCP discovery timeout.
272 1727:DHCP client tx discover(B).
273 1753:Flags was changed to be 0x0.
274 1810:Flags was changed to be 0x0.
275 1842:DHCP discovery timeout.
276 1846:DHCP client tx discover(B).
277 1872:Flags was changed to be 0x0.

278 1929:Flags was changed to be 0x0.
279 1961:DHCP discovery timeout.
280 1965:DHCP client tx discover(B).
281 1991:Flags was changed to be 0x0.
282 2048:Flags was changed to be 0x0.

Time = 2016-03-07 16:16:19 2051s

H-Ver = WR340G v3 0815311C : S-Ver = 4.8.13 Build 110701 Rel.58257n

L = 192.168.1.1 : M = 255.255.255.0

W1 = DUAL ACCESS : W = 85.238.73.241 : M = 255.255.255.0 : G = 85.238.73.241

Free=1995, Busy=27, Bind=25, Inv=2/1503, Bc=0/0, Dns=553, cl=160, fc=0/0, sq=0/0